

0032

OK
Internal
6/15/07

From: Steve Christensen
To: Pam Grubaugh-Littig
Date: 6/29/2007 11:11 AM
Subject: Fwd: emery subsidence
Attachments: Emery Subsidence 6-14-07.pdf

CC: Karl Houskeeper; Wayne Western
Pam,

Spoke with John G. this morning and discussed (among other things) their monthly visual inspection/subsidence reports. Russel Hardy from Consol had prepared a report (see attached) for the month of May and the report for June will be forthcoming. I took a look at it and I'm pleased. It's what I had in mind during the IBC permitting process. It's short and sweet and simply gets someone out there to take a look at the surface above the panels. So in short, they're doing what they're supposed to be doing. John and I discussed that in the future, he will e-mail the monthly subsidence reports to you and Karl H. (the inspector). If you'd like him to route the reports to other Division staff, let him know and he'll be glad to do that.

Steve


>>> "Gefferth, John" <JohnGefferth@consolenergy.com> 6/29/2007 9:40 AM >>>

John Gefferth
Consol Energy
P.O. Box 566
Sesser, Illinois 62884
618-625-6850 office
618-534-5151 cell
618-625-6844 fax
www.consolenergy.com (<http://www.consolenergy.com/>)

"This communication, including any attachments, may contain confidential and privileged information that is subject to the CONSOL Energy Inc.'s Business Information Protection Policy. The information is intended solely for the use of the intended recipient(s). If you are not an intended recipient, you are prohibited from any use, distribution, or copying of this communication. If you have received this communication in error, please immediately notify the sender and then delete this communication in its entirety from your system."

Consolidation Coal Emery Mine Subsidence Report for May 2007

5-8-07	No subsidence noticed over Panel 14 West. PB
5-19-07	No subsidence noticed over Panel 14 West. PB
5-21-07	No subsidence noticed over Panel 14 West. PB
5-31-07	Subsidence noticed over Panel 14 West. PB
6-4-07	1 inch cracks found above Panel 14 West where pillaring. Marked locations with GPS. PB



6-8-07

Few cracks over Panel 14 West pictures were taken. PB











6-13-07

Went to the surface with DOGM (Helfrich, Burton, and Christensen) and (Carter – landowner, Robertson – adjacent landowner, Knoop – JBR). All 3 springs SP-10, SP-11, and SP-12 were flowing. Two sets of cracks $\frac{1}{2}$ to $\frac{3}{4}$ inch wide were noticed across the road leading to the field. Landowner did mention at the South end of the long West Field the irrigation is not flowing to the end due to a high spot and low spot in the field. Walked the area with the land owner and could not find any cracks or signs of movement. However, area is above pillared out portion of the section.
RH